


Part Numbering XMH-J Series

XMH - J - X - X - X - X - X - X - X - X - X



Single PORT		Multiple PORT	
1	1*1	A:	2*1
2	1*2	B:	2*2
3	1*3	C:	2*3
4	1*4	D:	2*4
5	1*5	E:	2*5
6	1*6	F:	2*6
7		G:	2*7
8	1*8	H:	2*8

Notes: Plating Area

0: F μ 1: 6 μ 2: 15 μ 3: 30 μ 5: 50 μ 6: 3 μ